

9906 Reverse Battery Adapter Subassembly

contents

section 1	description/application	page 1
section 2	installation	page 1
section 3	functional schematic	page 2
section 4	specifications	page 1
section 5	testing and troubleshooting	page 1

1. description/application

1.01 The Tellabs 9906 Reverse Battery Adapter Subassembly (figure 1) is designed to regenerate reverse battery signals from the office end of a trunk circuit toward the station end. Currently, the 9906 Adapter is used exclusively on the Tellabs 7503 Dial Long Line (DLL) module to extend the range of reverse battery supervision on long loop Foreign Exchange (FX) or Off-Premise-Extension (OPX) circuits.

1.02 The 7503 DLL Module, when optioned with the 9906 Subassembly, regenerates signaling and supervision to increase the range of a loop-start central office or PBX line circuit, or a ground-start PBX-to-central-office trunk. The 9906 is most commonly used on the 7503 in toll diversion and answer supervision applications. For a more detailed description of the 7503 Module, refer to the Tellabs' 7503 DLL Module Practice.

1.03 The reverse-battery sensing circuitry of the 9906 Subassembly requires a minimum of 15mA of current from the central office, or from the next switching-side 9906 when used in tandem applications. This current requirement may therefore limit the 7503's maximum signaling range, which, when the 9906 is not provided, is determined by the range of the central office equipment.

1.04 As a subassembly, the 9906 Adapter mounts in "piggyback" fashion to the printed circuit board of the 7503 DLL module. Mounting the 9906 to the 7503 module is accomplished via two connectors (one 6-pin and one 3-pin) that provide electrical as well as physical connection. The 9906 Subassembly derives both its input power and extended reverse battery power from the host (7503) module.

2. installation inspection

2.01 The 9906 Reverse Battery Adapter Subassembly should be visually inspected upon arrival in order to find possible damage incurred during shipment. If damage is noted, a claim should immediately be filed with the carrier. If stored, the module should be visually inspected again prior to installation.

mounting

2.02 Installing the 9906 consists of plugging the Subassembly, via its two connectors, onto the 7503




figure 1. 9906 Reverse Battery Adapter Subassembly

module. The mating receptacles are located immediately behind the front panel of the 7503 module. Ensure that the connector pins are firmly seated in the receptacles.

2.03 The 9906 Subassembly has no options and requires no alignment. However, the 7503 module must be switch-optioned for use with or without the 9906. Switch S9 should be set to the *in* position if the 9906 Subassembly is used and to the *out* position if the Subassembly is not required. Refer to the 7503 DLL module Practice for more detailed information regarding switch optioning.

4. specifications

input power
-48Vdc, 40mA maximum

loop current detector sensitivity
minimum 15mA loop current

reverse battery detection delay
100ms

weight
1.5 ounces (42 grams)

dimensions
2.0" (5.1cm) x 3.0" (7.6cm) x 0.6" (1.5cm)

mounting
mounts as subassembly on Tellabs 7503 Module

5. testing and troubleshooting

5.01 This Testing Guide may be used to assist in the installation, testing or troubleshooting of the 9906 Reverse Battery Adapter Subassembly. The Testing Guide is intended as an aid in the localization of trouble to a specific unit. If a unit is suspected of being defective, a new unit should be substituted and the test conducted again. If the

4951 Indiana Avenue, Lisle, Illinois 60532
Tel labs Incorporated
Telephone (312) 969-8800 TWX 910-695-3530

is in warranty, no invoice will be issued.
Repair the unit and ship it back to you. If the unit
repairs to administrative paperwork. Tel labs will
follow your company's standard procedure with
enclose an explanation of the unit's malfunction.
Attn: repair and return dept.


Lisle, Illinois 60532

4951 Indiana Avenue

5.06 Return the defective 9906 Subassembly
repair and return

and ship the equipment prepaid to Tel labs.
the replacement unit to the carton being returned;
label provided with the replacement unit (this is your return auth-
orization); affix the defective unit (this is your return auth-
orization) with the replacement 9906 and enclose it
included with the replacement units' carton; sign the packing list
the replacement units' carton; package the defective 9906 in
ped at no charge. Package the replacement unit will be ship-
ped at no charge. If the warranty period of the defective unit
has not elapsed, the replacement unit will be shipped
you. If the warranty period of the defective unit
notificaion, we shall ship a replacement 9906 to
terminie the issue of the 9906 in question). Upon
the BX9906 part number (from which we can de-
should include all relevant information, including
below], or twx [910-695-3530]. Notification
be turned to Tel labs for repair or replacement. It is
strongly recommended that no internal (compo-
nent level) testing or repairs be attempted on the
substitute unit should be considered defective and
returned to Tel labs for repair or replacement. It is
recommended to Tel labs for repair or replacement. It is
not authorized testing or repairs may void
9906. Unauthorized testing or repairs may void
5.02 To test the 9906 Subassembly, the Sub-
assembly must be installed and tested in conjunc-
tion with the 7503 Module. Refer to the 7503
Module's Testing Guide. Checklist for detailed
information on testing procedures relevant to the
9906 Subassembly.

5. block diagram



5.05 If a defective 9906 is encountered, notify replacement
Tel labs via telephone [(312) 969-8800], letter [see
5.05 whenever time is a critical factor (e.g., service
method, the replacement procedure should be fol-
lowed when ever repair and return. Because it is the more expedient
repair and return, the customer should be fol-
lowed when ever time is a critical factor (e.g., service
outages, etc.).

5.04 If a 9906 is diagnosed as defective, the site
at (312) 969-8800 for further assistance.
the Checklist, contact Tel labs Customer Service
5.03 If a situation arises that is not covered in
at (312) 969-8800 for further assistance.

5.04 If a 9906 is diagnosed as defective, the site
at (312) 969-8800 for further assistance.

5.03 If a situation arises that is not covered in
the Checklist, contact Tel labs Customer Service
at (312) 969-8800 for further assistance.

5.02 To test the 9906 Subassembly, the Sub-
assembly must be installed and tested in conjunc-
tion with the 7503 Module. Refer to the 7503
Module's Testing Guide. Checklist for detailed
information on testing procedures relevant to the
9906 Subassembly.

5.02 To test the 9906 Subassembly, the Sub-
assembly must be installed and tested in conjunc-
tion with the 7503 Module. Refer to the 7503
Module's Testing Guide. Checklist for detailed
information on testing procedures relevant to the
9906 Subassembly.

5.02 To test the 9906 Subassembly, the Sub-
assembly must be installed and tested in conjunc-
tion with the 7503 Module. Refer to the 7503
Module's Testing Guide. Checklist for detailed
information on testing procedures relevant to the
9906 Subassembly.

5.02 To test the 9906 Subassembly, the Sub-
assembly must be installed and tested in conjunc-
tion with the 7503 Module. Refer to the 7503
Module's Testing Guide. Checklist for detailed
information on testing procedures relevant to the
9906 Subassembly.