

RECTIFIERS
J86207A, D, G, H, K, L, M, AND U
OPERATING METHODS

1. GENERAL

1.001 This addendum supplements Section 169-230-301, Issue 8. Place this pink sheet ahead of Page 1 of the section.

1.002 This addendum is issued for the following reasons:

- (a) To specify a replacement cord for one that has been rated "Mfr. Disc."
- (b) To identify those rectifiers that have been rated "Mfr. Disc."

This addendum does not affect the Equipment Test List.

2. CHANGES TO SECTION

2.001 On Page 1, add the following paragraphs.

1.07 Rectifiers J86207A, K, and U have been rated "Mfr. Disc."

1.08 Power cord and plug KS-7993 have been rated "Mfr. Disc." and have been replaced by 3-wire cord and plug KS-16935, L1 on the J86207K rectifier.

NOTICE

Not for use or disclosure outside the
Bell System except under written agreement

Printed in U.S.A.