


FIG. 1

AS SEEN FROM REAR




NOTES:-

1. SHELF JACK UPOINTS 59 AND 61 IN FIG. 1 TO MAKE CONTACT WHEN RELAY SET IS REMOVED  
SHELF JACK UPOINTS 9 & 11 IN FIG. 1 AND 59 AND 61 IN FIG. 4 NOT TO MAKE CONTACT WHEN RELAY SET IS REMOVED
2. STRAP U65 TO UPOINT ASSOCIATED WITH BANK CONTACT CORRESPONDING TO INITIAL DIGIT OF MULTI-PARTY LINE NUMBERS SEE GBW. 13650  
STRAP U61 TO UPOINTS ASSOCIATED WITH BANK CONTACTS CORRESPONDING TO UNALLOTTED DIGITS OF MULTI-PARTY LINE NUMBERS SEE GBW. 13650
3. STRAP U30-U32 AND U62-U64 WHEN JUNCTION TERMINATES ON MANUAL BOARD
4. ALL WIRING NOT OTHERWISE SPECIFIED TO BE 20S.W.G.

FIG. 4

AS SEEN FROM REAR



DISCRIMINATING SELECTOR LINEFINDER & ALLOTTER FOR MULTIPARTY LINE UNIT U.A.X. N.Z. 13R			
FIG. 1 - DT. ETH. TO U22 DELETED. U56 TO D57/O MADE U56 TO D57/O 2	20.12.54	cur	
(34594)	1	20.12.54	
AMENDMENT PARTICULARS	ISSUE DATE	APP'D	50V C
N.Z.P.O.	WS AM	13/1/54	GBU. 13650.

0  
5 Centimetres  
10  
15  
20  
25  
30