



- NOTES:-**
1. FUSE 1.5A AMP PER CIRCUIT.
 2. WHEN CONTINUOUS RINGING IS USED. INSERT STRAPS 2-3, 5-6.
 3. ALL WIRES UNLESS OTHERWISE SPECIFIED TO BE 25 S.W.G.
 4. WHEN COMMON EQUIPT GBW 13760 OR EQUIV IS NOT FITTED INSERT STRAPS SHOWN — 3 — 3 —

REVERSING (KR)	MULTI PARTY RING START (KMP)
TEST BELL (KTB) + RING IND. OR 2 PARTY (KX)	
SPEAKING BATTERY (KB)	HOLD SERVICE LINE (KH) + HOLD TESTER (KHT)
VOLT METER REVERSING (KVR)	DIAL TEST (KD) TEST IN (KTI) + TEST OUT (TO)
EARTHING (KE) + RING MULTI PARTY (KMP)	VOLT METER (KV)
VOLT METER BATTERY CUT-OFF AND REC. NEG. (KN)	TEST CIRCUIT SPEAKING (KS)

BATT. BK. FUSE — D5e - Ie - DST 2 - BL1b - KNI - LPIb		TO SERVICE LINE	
EARTH RETH. BAR — D5a - DS2 - Ia - R2a - KMP2 - KX2		— KE4 - KN23 - KHL22 - KHT31 - TAG6.	
SLOW RELEASE		SLOW OPERATE	
LINE TESTING CIRCUIT			
U.A.X. NZ13			
AMENDMENT PARTICULARS		ISSUE DATE	APPD REF
NZRO!		2.8.54	50V C
GBW 13870			