

RELAY CODES & COMPONENTS LIST, GBW 16880

DAX NZ13 - 1/2 JUNCTION FROM PARENT OR NON-DEPENDENT  
EXCHANGE - WITH OR WITHOUT DIAL TONE SUPPRESSION.



RELAY	BCC CODE	DIAG FIG	NOTES	COMP'D DESIGNATION	BPO CODE	NOTES
1BA 2BA	20541			R1A R1B	N°9	
1LA 2LA	13705P			R2	N°12	
1AA 2AA	1630					
2HB 1HB	1630			DI TO 5 D6 & D7		CV 8308 OR DA000 (LUGS 400) IN 4003
1K 2K	1904			SCA SCB	N°121A	
1P 2P	40219			SCC		NZPO S.L. N° LH 814
1JA 2JA	1397					
1CD 2CD	16486					
					EC 43235	2CCT FAST LOOP DETECTOR

NOTES: - A SPECIAL FACTORS OF SAFETY B SPECIAL ADJUSTMENTS C CIRCUIT POINTS OR MODIFICATIONS

LAYOUT  
 2 CCTS. PER PLATE.

MOUNTED AT REAR

1LA 1HA 1P 1JA 2LA 2HA 2P 2JA  
 1BA 1HB 1K 1CD 2BA 2HB 2K 2CD



SCC  
 MTD AT REAR  
 1CD (2CD)

NZPO  
 (39692) 30-8-71 DLM

ISSUE APP  
 REDRAWN  
 LAYOUT REVISED.  
 REL. A. HSD 202 DELETED.  
 TOGETHER WITH 13.44  
 15 RECOMMENDED  
 CODE OF CD RELAY WAS 5191  
 LA 1826  
 11 WAS DESIGN MARKED M81.  
 ISSUE 3 8-6-68  
 CODE OF CD RELAY  
 WAS 15219.  
 DI TO DS ADDR  
 ISSUE 4 8-10-68  
 P RELAY WAS 15210.  
 ISSUE 5 22-10-68  
 D6 & D7 ADDR  
 (144 950)  
 13 SA 13 9-16 68N  
 SCC, R4, D8  
 R5A & B, 1A  
 2A ADDR  
 NZMUE (1-322)  
 155 5B 14-11-80 UR  
 NZM X 9  
 (54422)  
 155 5C 18-12-68 6505  
 MINOR AMD  
 (54461)  
 155 5D 29-3-68 206

ORIGINATED BY A.T&EO  
 DATE 7-1-66  
 SIGNED FOR COMMITTEE AW