

The manufacture of the following receivers has been discontinued, and it is not considered necessary to maintain complete information in the catalog.

For information on code numbers not listed below, see other cards on Receivers.

Code No.	Repl by No.	Code No.	Repl by No.	Code No.	Repl by No.
122	—	196W	551	559A	718B
125	—	(*)509	716C recom	563A	(e)
127	—	525	(c)	567A	—
128	—	528	(d)	574A Type	—
128A	—	528C	727A	706A	—
131	(a)	528BW	528	708A Type	—
131BW	131	541	—	710B Type	(f)
133	—	544	—	711A	KS-14719
144	706A	551	—	716C	—
146	(b)	551W	551	716H	—
146A	717A	557	557B	720A	KS-14704
157	—	557B Type	—	730A-58	—
192	—	558	558B	730A-61	—
196	551	558B	—		

(*) Codes added this issue.

(a) Replaced by HA2 receiver unit, P-224711 case assembly and P-456236 cap.

(b) Replaced, except for wall sets and dial system automatic sender testing equipment, by No. 146A receiver and replaced by No. 718A receiver for use in dial system automatic sender testing equipment.

(c) Replaced by No. 716C receiver plus No. 11A headband.

(d) No. 716A, B, D or E recommended.

(e) Replaced by No. 528 less headband.

(f) KS-14720 head set recommended.

Property of AT&T

Printed in U.S.A.