

[illegible]

Code No.	Ringer	Gongs	Con- denser	Induc- tion Coil	Switch- hook	Trans. Bracket	Cords	Resist- ance	Retard. Coil	Trans- mitter	Re- ceiver
653BB	68J	*2-29C	1-49A 1-49B	62	40AL	7A	2-T1A 9-7/8" long	63H	54S	+337	+567A

+ Not furnished with equipment. Must be ordered separately.