SHEET 1 OF 1

RELAY CODES & COMPONENTS LIST, GBW 12890

SUPERVISORS INCOMING LINE FROM SWITCHBOARD. S.C.S.

RELAY	BCC CODE	DIAG FIG	NOTES
I	2022	1A	
SS	4074	1A	
SC	4116	1A	
SM	10221	1A	NOTE 1.
A	6156	1A.	

COMPT DESIGNATION	BPO CODE	NOTES
C1	102C	* FIG 1A
C2	102C	* FIG 1A
C3	102C	* FIG 1A
R1	N°12	FIG 1A
R2	N°12	FIG 1A.
KS+KH	N°212.	FIG 1B

NOTES - A SPECIAL FACTORS OF SAFETY B SPECIAL ADJUSTMENTS C CIRCUIT POINTS OR MODIFICATIONS

LAYOUT

ALTERNATIVE LAYOUT NOT USING SUFFIX 'A' TYPE CONDENSERS C1.C2.C3.*

I	SC	A	C1	C3
SM	SS	R1 R2	C2	+

I	SC	A	C3
SM	SS	C1 C2	R1 R2

* ON EARLY EQUIPMENTS CONDENSERS C1, C2 & C3 ARE BPO N°102A

NOTE 1. RELAY 'SM' WAS 6028. THIS RELAY HAS BEEN CHANGED TO FACILITATE MANUFACTURE. NO RE-ADJUSTMENT IS NECESSARY ON SITE TO RELAYS CODED 6028.

N.Z.P.O. (6934) 17.10.63 B.6. ISSUE 1

ORIGINATED BY	AT&E.C°L(D)	
DATE	3-9-63	
SIGNED FOR COMMITTEE		

ATP 1960 REV. E451