RELAY CODES & COMPONENTS LIST GBW 13410

LISTENING-IN-LINES TO SWITCHBOARD POSITIONS SUPERVISORS OR POSTMASTERS TURRET 2000 TYPE

DIAG FIG	BCC CODE	RELAY	NOTES
FIG1	HS518	K	B1
"	6001	CT	
"	50114P	LJ	A1 SPGS 21 & 22 SPARE
"	2017	G	

COMPT DESIGNATION	BPO CODE	NOTES
TR1	3/43A	
MR1	2/2AZ	
R1	Nº 35B	FIG 2
KL1	207	
SWA		AB METAL PRODUCTS LTD. OAK TYPE H 4 SECTION 11 POSITION ROTARY SWITCH

NOTES:- A. SPECIAL FACTORS OF SAFETY. B. SPECIAL ADJUSTMENTS C. CCT. POINTS OR MODIFICATIONS

LAYOUT.



NZPO

APP	
ISSUE 1. 22-3-61 G WAS 2017. R1, L & C1 DELETED LAYOUT REVISED	
ISSUE 2. 6-12-62 G WAS 4016 LJ SPRGS 21 & 22 WERE NOT SPARE	
ISSUE 3 29-3-63 R1 WAS P.O. Nº 12	
ISSUE 4 23-5-63 NAME & CODE OF SWA AMENDED (74750)	
ISSUE 5 14-6-63	

ORIGINATED BY	AEI
DATE	22-3-61
SIGNED FOR COMMITTEE	