

TELEPHONE SETS
500, 501, 554, AND 556 TYPES
IDENTIFICATION, INSTALLATION, AND MAINTENANCE

1. GENERAL

1.001 This addendum supplements Section 502-510-100, Issue 6.

1.002 This addendum is reissued to revise MD information on telephone sets and revise mounting information for wall telephone sets.

2. IDENTIFICATION

The following changes apply to Part 2 of the section.

(a) Table A—revised

3. INSTALLATION

The following changes apply to Part 3 of the section.

(a) (b)—revised

(b) Mounting Wall Sets

- Several holes are provided in the baseplate for more flexibility in mounting to minimize backboard use.
- ♦ Early production sets have a baseplate which does not provide the proper hole arrangement for fastening directly to conduit outlet boxes, 157A adapter, 63A or KS-19407L1 prewire brackets.♦
- ♦ Refer to Section 463-130-200 for information on fasteners suitable for mounting wall-type sets directly to wall surfaces.♦

TABLE A
TELEPHONE SET COMPONENT PARTS

SET	CODE	COMPONENT							
		DIAL	APP BLK§	NET	RINGER	HANDSET	MTG CORD	ELECTRON TUBE	HOUSING ASSY
500	A/B*	9C†	95C	425A¶	C4A††	G1A or G3A	D3BN		P-80D200
	C/D			425E**					P-80D500
	E/F						D4BJ		P-80E100
	H*			425A			D3BN		P-80D200
	J/K*		95C				D4BJ		P-80E100
	L/M			D10P			P-80D200		
	P*			D4BJ			P-80E300		
	R/S		9H‡	95C					P-81K000
	U*		9C†						P-80E100
	W			95C					
	Y								
501	A/B*	9C†	95C	425A¶	C4A††		D3BN	426A	P-80D200
	C/D			425E**					P-80D500
	F			425A					P-80D200
	J/K*		95C						P-80E100
	P*			425E**			D4BJ		P-80E300
	U*								
554	A/B		95C		C4A		426A	P-80F400	
556	A/B								

* MD

¶ Includes 311A equalizer

† Replaces 7C or 7D dial

** Replaces 425B network

‡ Replaces 7G or 7H dial

†† Early models had C2A ringer

‡ Replaces 95A or 95B apparatus blank

‡† Early models had C3A ringer