STATION PROTECTION

MAINTENANCE

1. GENERAL

1.01 This addendum is issued to clarify instructions concerning protection requirements.

1.02 Inspections are required on all maintenance visits to see that the station protection complies with the specifications contained in BSP 638-215-300.

1.03 When 58AP or older type protectors are found on maintenance visits they shall be replaced with the proper type protector as specified in BSP 638-215-300. This requirement may be deferred during heavy work load periods when authorized by local supervision. In such cases it will be necessary for the craftsman to prepare a Plant Upkeep Order, Form 694 indicating the work to be performed.