

REPLACING PAGE ADDENDUM

Filing Instructions:

1. REMOVE FROM THE SECTION THE PAGES NUMBERED THE SAME AS THOSE ATTACHED TO THIS PINK SHEET.
2. INSERT THE ATTACHED PAGES INTO THE SECTION IN THEIR PLACE.
3. PLACE THIS PINK SHEET AHEAD OF PAGE 1 OF THE SECTION.

**TROUBLE LOCATION METHODS
USING VOICE-FREQUENCY SWEEP TEST SETS
ON SUBSCRIBER CABLE PAIRS**

1. GENERAL

1.001 This addendum supplements Section 330-450-102, Issue 2. The attached pages must be inserted in the section in accordance with filing instructions above.

1.002 This addendum is issued to revise Fig. 1 for change in resistor value in the sleeve lead of the modified 565GK switch unit and to show proper cross-connection in the modified 565GK

instrument in Fig. 2. This addendum does not affect Equipment Test Lists.

2. TESTING ARRANGEMENTS

The following changes apply to Part 2 of the section:

- (a) Fig. 1—revised
- (b) Fig. 2—revised

Attached:

Page 4 dated June 1971, revised

Page 5 dated June 1971, revised