

RESISTOR—CAPACITOR TIMED RELAY INTERRUPTER TESTS

1. GENERAL

1.001 This addendum supplements Section 040-009-501, Issue 2.

1.002 This addendum is issued to revise 2.06.

2. CHANGE TO SECTION

ISSUE 1 CHANGE

2.001 On Page 1, change 2.06 pulse checking test set, J94725 to J94723.