

BELL SYSTEM PRACTICES
Station Installation
and Maintenance

ADDENDUM C41.107
Issue B, 11-1-46-C

MAGNETO STATIONS
FEDERAL SET

1. GENERAL

1.01 This addendum, which supplements Section C41.107, Issue 1, and replaces Issue A, is re-issued to cancel the reference to Federal apparatus parts for maintenance purposes and to cover limitation of the use of this set on heavily loaded magneto lines and its application to Issue 1 of the section. This issue should be retained with subsequent issues of the section until notice is given to cover its reissuance or cancellation.

1.02 Paragraphs 1.06 and 4.04 of this addendum supplement Part 1 and 4.04, respectively, and 6.01 replaces 6.01 of the section.

1.06 Since Federal magneto sets are equipped with 3-bar hand generators (the approximate equivalent of the W.E. Company 3-bar generator) these Federal sets should not be installed on heavily loaded magneto lines, or at magneto stations which would usually require a 5-bar generator.

4. CONNECTIONS

Ringer Connection Limitations:

4.04 Where the limits specified in this paragraph of the section are exceeded, it will be necessary to use a standard 5-bar hand generator set such as the 417P set.

6. MAINTENANCE

6.01 The piece part listings, associated with 6.01 of the section, should be disregarded for replacement purposes, as these parts are not being made available for field repair purposes. In cases where trouble develops in these sets where replacement parts are involved, except for cord and hand set changes which may be made in the field, the complete telephone set should be replaced and returned for repair.