

**BELL SYSTEM PRACTICES**  
**Station Installation and Maintenance**

**ADDENDUM C32.560**  
**Issue 1, April, 1956**  
**AT&T Co Standard**

## **TELEPHONE SETS**

### **554, 556, AND 558 TYPES**

### **INSTALLATION AND MAINTENANCE**

#### **1. GENERAL**

1.01 This addendum supplements Section C32.560, Issue 1.  
It is issued to add information on the C4A ringer used  
in these telephone sets.

#### **3. MAINTENANCE**

3.01 Change to read: All components of these sets, except  
the early model C4A ringers, are interchangeable with  
the 500-type telephone sets. The frames on all C4A ringers  
manufactured after January 15, 1955 have been changed in  
design so that they will not interfere with the free movement  
of the volume-adjusting arm as did the earlier model. The  
maintenance of these components is covered in other sections  
of the C practices.

**ADDENDUM**  
**C32.560**

Page 1  
1 Page

**TELEPHONE SETS**  
**554, 556, AND 558 TYPES**  
**INSTALLATION AND MAINTENANCE**