


Centimetres 0 5 10 15 20 25 30



- NOTES:-
1. FUSE:-1.5A PER 10 CTS.
 2. ALL WIRING NOT OTHERWISE SPECIFIED TO BE 23 S.W.G. M.A.R. PLATE WIRING TO BE 23 OR 25 S.W.G.
 3. WHEN I.D.F. TERMINATIONS ARE NOT REQ'D DELETE FIG. 2 AND CONNECTIONS SHOWN THUS -x-x-x- AND ADD CONNECTIONS SHOWN THUS -|-|-|-|

BATT. BK. 20S.W.G. FUSE—YA2 ETC
 ETH. R. 20 S.W.G. ETH BAR—S22-SQ-54 ETC
 SMD ETC

TO BATT VIA PILOT
 GBW 11440 OR EQUIV.

MAN. BOARD.
 EXPLANATORY
 ONLY.

FIG.1 M.A.R.

FIG.2


TEST DESK
 OR RACK
 EXPLAIN ONLY

SUPERSEDED BY GBW 12950

SUPERSESSION NOTE ADDED (5499B) 3 3.12.62 DMH
 NOTE 3 & ASSOC. WIRING WAS NOT SHOWN (947) 2 26.3.53 GPH

AMENDMENT PARTICULARS

ISSUE	DATE	APPD	REF
1			



TEST DESK OR RACK
 INCOMING LINE FROM
 MANUAL BOARD (6CS)
 2000TYPE

N.Z.P.O.

DRAWN	CHECKED	WIRING	CIP/CQT
928	985	985	SMV

GBW 11820

SIZE	F	BOX	H
------	---	-----	---