

0
5 Centimetres
10
15
20
25
30




FIG. 1. TEST DESK OR RACK
TO OTHER POSNS AS REQUIRED.

FIG. 1A. MANUAL BOARD







FIG. 4. TEST DESK OR RACK
TO OTHER POSNS AS REQUIRED.

FIG. 4A. MANUAL BOARD



- NOTES:-
1. FUSING:- FIG. 3. FUSE 1.5A SERVING TELE. CIRCUIT
 2. ALL WIRE BEARING A COLOUR CODE TO BE 23 S.W.G. UNLESS OTHERWISE SPECIFIED
 3. FOR WIRING OF LEADS SHOWN \emptyset SEE GBW 11480 OR EQUIV.

BATTY. BK. BATTY. TAG OR FUSE SERVING TEL. CCT. — YAC ETC.
ETH. R. POSN. ETH. OR ETH. BAR. — YBI ETC.

ORDER WIRE (KOW)
3

NOT TO BE USED FOR NEW WORK

NOTE "NOT TO BE USED FOR NEW WORK" ADDED (50595)				4.		11-12-62		DBM	
REDRAWN FIGS. 4, 4A & 5 ADDED (68026)				3.		19-10-56		RDM	
TEST RACK CONDITIONS ADDED				2.		17-10-56		4	
AMENDMENT		PARTICULARS		ISSUE DATE		APPD. REF.		SIZE M 50V C	
N.Z.P.O.		PAC		5/11/63		23-7-56		GBW 11880	