



**NOTES:**

- FUSING 1-5A PER CIRCUIT.
- ALL WIRING TO BE 25 SWG UNLESS OTHERWISE SPEC'D.
- SHIELD JACK U POINTS 9&11 TO MAKE CONTACT WHEN RELAY SET IS REMOVED.
- STRAP U14-27 WHEN REPEAT METERING EQUIPMENT IS NOT PROVIDED.
- Ø FOR WIRING SEE GBW10640 OR EQUIV.

BATT. BK 22 SWG FUSE (18) U12  
 ETH. R. 22 SWG ETH. BAR (1A) U11  
 BATT. W. U12-5Ae-De-MBa-MBe-MAB-MAc-NRe-MMe-GMe-DDe-ZMe-SCe-MCb-MCe-SBa-PRc-R3b-R2b-R1b  
 EARTH. R. U11-D1-M1-DB24-DAg-MMeJ1-CH22-CH24-CH26-ZM1-CD2-SC1-PR2-R5g-TJ1

FROM REPEAT METERING EQUIPMENT GBW12451 OR EQUIV.

5' METER PULSE Ø FIG 18A  
 5' METER PULSE Ø FIG 19A  
 2' METER PULSE Ø FIG 18A  
 6 SECOND EARTH Ø FIG 22A

AMENDMENT PARTICULARS

ISSUE DATE APP'D

SIZE M 50V E

GBW 14361

NZPO

DRAWN CHECKED WIRING CIRCUIT

JN

14