

FIG.1 TEST RACK
1 PER TEST SELECTOR

FIG.2A M.A.R.
1 PER TEST SELECTOR







FIG.2B
M.A.R.
NOTE.2

- NOTES:
1. FUSING: 1.5A FIG.1, 1.5A FIGS.2A & 2B.
 2. FIG.2B IS REQD. ONLY WHEN TEST SELECTOR IS FITTED AT REMOTE EXCHANGE.
 3. LEAD 'E' IS REQD. ONLY WHEN CCT. IS CONNECTED TO LOCAL SWITCHING CONTROL CIRCUIT.
 4. WHEN RURAL LINE TEST FACILITIES ARE SPEC'D. PROVIDE FIGS.3 & CONNS. SHOWN -1-1- & OMIT CONNS. SHOWN -2-2-.
 5. ALL WIRING TO BE 0.5mm UNLESS OTHERWISE SPECIFIED.
 6. Ø FOR WIRING SEE GBW 10690 OR EQUIV.

PROOF



TEST RACK
LINES TO TEST SELECTOR
(GEO-THERMAL AREAS)

A	23.4.80	AG	17036		RETRACED
T	9.2.67		58280	DJ.8	
ISS DATE	DEL	DC	ORDER	CKD	APD
DRN: 55	CKD	ORIGIN: 55			
TCD: A.G	APPD	STANDARD: ATW22001			
NZPO ENGINEER-IN-CHIEF, WELLINGTON					
SHT 1 OF 1		GBW 19020			
SIZE A2					

