



RELAY CODES & COMPONENTS LIST, GBW 13630
 INCOMING JUNCTION FROM U.A.X. NZ. No.13. (PARENT),
 RELAY SET FOR S.C.S. SWBD.

RELAY	BCC CODE	DIA FIG	NOTES	COMPT DESIGNATION	BPO CODE	NOTES
G ^B A	2312			TRI	BM 4177/3	S.T.C. CODE.
W ^{CB} A	2308			CI	MC 102	
R ^{CH} _	2404		B	C2	MC 102	
R ^{LA} _	70566		B	MR1	1/12A	
R ^{LB} _	70566		B	MR2	1/12A	
W ^{MH} B	2322		A = FOS.3G.	MR3	1/12A	
W ^{PL} B	70444			RI	No.9.	
W ^S A	6198			R2A	No.9	
W ^{SC} B	1043			R2B	No.9.	
W ^{SS} A	2478			R3	No.9	
G ^{SW} (B)	60970		ON EARLY EQUIP SW WAS 73880	R4	No.9.	
				R5	No.9.	
				R6	No.15GD.	MOUNTED ON C2.
				R7	No.15GD.	MOUNTED ON C2.

NOTES - A SPECIAL FACTORS OF SAFETY. B SPECIAL ADJUSTMENTS. C CCT. POINTS OR MODIFICATIONS.

LAYOUT



FRONT VIEW

≠ RELAY GUARD

NZPN

ISSUE 5.
 CRD WAS 2 SHEETS
 SHT.1.20.5.58 (155.5)
 SHT.2.24.3.59 (155.3)
 RELAY SW. WAS 73880
 ISS G.18.2.60 REPLACEMENT TCG INCORP. (03796) JHE
 155.6 4.12.74

ORIGINATED BY	S.T.C.
DATE	5.10.53.
SIGNED FOR COMMITTEE	D.H.C.

Centimetres

5
10
15
20
25
30