

RELAY CODES & COMPONENTS LIST, **GBW 14950**

UAX NZ13 NIGHT SWITCHING TO 2VF ADAPTOR

RELAY SET

RELAY	BCC CODE	DIAG. FIG.	NOTES	COMP. DESIGNATION	BPO CODE	NOTES
PD	1133	1		R2	N°9	} FIG. 1 MOUNTED ON C1.
PC	20906	1		R3	N°9	
PB	11357	1		(R4)	26GC	
PE	11452	1		C1	N°102C	
NS	11359	1		KNS	N°68	} FIG. 2.
IA	11354	1		R1	N°9	
DP	10984	1		(MR1)		HS1009 - FIG. 1.
BP	11358	1		(MR2)		HS1009 - FIG. 1.
BR	20908	1		C2	L681833A OR EQUIV	FIG. 1. (40 mf ± 20% TANTALUM)
S	15591	1		R1	N°12	FIG. 1.
CB	4269	1		R1	9	FIG. 3.
SR	11355	1				
RL	78326	3				

NOTES: - A SPECIAL FACTORS OF SAFETY B SPECIAL ADJUSTMENTS C CIRCUIT POINTS OR MODIFICATIONS


R/H UPRIGHT OF RACK.

LAYOUT
RELAY SET.

1RI
2RI
1RL
2RL
3RI
4RI
1RL
4RL

PD PC
 DP PB
 NS BP
 IA SR
 PE BR
 CB S

CONDENSER BOX LAYOUT.



NZ.P.O.
 (69041) 219.63. 36.

ISSUE 1 CODE OF'S RELAY WAS BCC 11379	ISSUE 2: 27-4-64. FIG. 1. R1 DELETED & R5 & C2 ADDED FIG. 3 ADDED.	ISSUE 3: 4-4-65. R1. FIG. 1 WAS R5 COND. BOX LAYOUT FOR R2-3-1 REVISED.	ISSUE 4: 27-5-65 C2. FIG. 1 CODE AMENDED (72939)	ISSUE 5: 20-1-67.	ORIGINATED BY A.T.&E. LTD.
					DATE 26-6-63
					SIGNED FOR COMMITTEE H.B.