


RELAY CODES & COMPONENTS LIST, **GBW 15011**
 'O' LEVEL RELAY SET FROM INCOMING I.V.F. CIRCUIT VIA
 TANDEM GROUP SELECTOR (SLEEVE CONTROL MANUAL BOARD)
 2000 TYPE.

RELAY	B.C.C. CODE	DIAG. FIG.	NOTES	COMPT. DESIGNATION	BPO CODE	NOTES
B	20527		CI	R1-3	9	
BA	50033			R4&5	12	
D	71773			C1 & 2	MC 103C MK2	
DS	5903			C3 & 4	102	
IA	1524		RETARD	MR1	2N/6A	
LS	7542			MR2	1/6A	
NR	7597			MR3&4	1/12A	
PC	2583			MR5	DA000	JOSEPH LUCAS CODE.
S	5878		B1	TJ	21E MK4	
SD	7557		B2	PLUG	3205	
SS	1208					

NOTES:- A. SPECIAL FACTORS OF SAFETY. B. SPECIAL ADJUSTMENTS. C. CCT. POINTS OR MODIFICATIONS.
 B1 TEST & RA FIGURES NOTE C2. ON EARLIER EQUIPMENT
 B2 " & " MR5 WAS CV7023.
 CI REL. B. SPG 23 SPARE THE CHANGE IS NOT
 & UNWIRED. RETROSPECTIVE.

LAYOUT.



FITTED W/- GUARD
 RECT. MR5 MTD. IN
 WIRING W/- SS RELAY

NZ.P.O. (82769) 17-7-64 *AB*

ISSUE 1. APPR 16-6-64 MR5 CHANGED FROM CV7023 AND NOTE C2 ADDED. (72662) <i>ab</i>	ISSUE 2 17-2-67	ORIGINATED BY	A. E. I.
		DATE	16/6/64
		SIGNED FOR COMMITTEE	<i>Ash</i>