

RELAY CODES & COMPONENTS LIST, GBW 15200
MANUAL BOARD CIRCUIT
50/1200 LINE P.A.B.X.

RELAY	BCC CODE	DIA FIG	NOTES	COMPY DESIGNATION	BPO CODE	NOTES
DA	60635	1A		1C	P.O. 3/16 COIL INDUCT	FIG. 1A
DN	60622	1A		MRI	2/2 AZ	FIG. 1A
DS	60639 P	1A		C1	102	FIG. 1A
PR	61545 P	1A		C2	"	"
WP	HS 706	1B	BI	C3	"	"
				C4	"	"
				C5	"	"
				R1	6	FIG. 1A IN WIRING
				R2	6	" " "
CT	6818	6		R3	9	FIG. 7
				R4	9	FIG. 6
				R5	9	"
				R6	12	FIG. 1A
				R7	6	FIG. 4
				R8	6	FIG. 2
				R9	6	" IN WIRING
				R10	6	FIG. 1A " "
				R11A	12	FIG. 1B
				R11B	12	"
				R12	12	FIG. 1A
				R13	6	FIG. 1B IN WIRING
				RX1	No. 2 NON LINEAR	FIG. 1A " " ON DA

NOTES - A SPECIAL FACTORS OF SAFETY. B SPECIAL ADJUSTMENTS. C CCT. POINTS OR MODIFICATIONS.

LAYOUT
FRONT VIEW



MOUNTING B.P.O. F.151/18AH

N.Z.P.O.
15 4-70
(21918) I.S.R.

ISSUE 18-3-63 APP
WAS CR.DS.
PR RELAY WAS
BCC 50164 P
GH RELAY
DELETED
RESISTORS
REARRANGED
ISS. 2 1964
R14 DELETED. F.E.
RX1 ADDED.
ISS. 3 1969.

Ref. RE/AC 21, 29.12.69

ORIGINATED BY	S.T.C.
DATE	18/3/63
SIGNED FOR COMMITTEE	R.E.D.