

# RELAY CODES & COMPONENTS LIST, GBW 15570

LOOP TO N.Z. SIGNALLING SYSTEM A.C. N°1 CONVERSION RELAY SET

WITH BRIDGE SWITCHED OUT WHEN SEIZED BY AN A.C. N°1  
SIGNALLING CCT.


DIAG FIG	BCC CODE	RELAY	NOTES	COMPT DESIGNATION	BPO CODE	NOTES
	HSD702	A	B	R9	N°6	MTD. ON C4
	HSD513	AA	B	R1/2/3	N°9	
	50.026P	AB		R4/5/6/7	N°15	
	HSD515	AX	B	R8	N°9	
	50.028	B		C1	102C	
	50.025	BR		C2	102C	
	50.024	CD		C3	101	
	50.027	D		C4	102C	
	4073	DD		MR1	1/12AZ	
	2583	NR		MR2	1/12AZ	
	HSD512	TX	B	T1	AE CODE 415 A	SINGLE LAY SPACE (NOTE 1)
	6010	DA		R10	N°12	
				R11, R12	N°15	
				R13, R14		

NOTES:- A.SPECIAL FACTORS OF SAFETY.B.SPECIAL ADJUSTMENTS C.CCT. POINTS OR MODIFICATIONS

## LAYOUT.

### FRONT VIEW

	T1	R1/2/3
	R8,4,5,6,7.	A
*	AB	AA
	B	AX
	CD	TX
*	D	DD
	NR	BR
		DA



MTG.RS2/2000 TP204 SHT.5 FIG.1

\* GUARD

NOTES:- 1. ON SOME EARLY EQUIPMENTS T1 WAS AE1 CODE 392A.

N.Z.P.O.

ISSUE 1 29-4-59 EQUIP. LAYOUT WAS NOT SHOWN	ISSUE 2 30-12-60 T1 CODE WAS 392A & NOTE 1 ADDED.	ISSUE 3 9-1-62 TX WAS HSD 720 C4 WAS 101. R10 TO R14 ADDED	ISSUE 4 22-2-62 DA ADDED POSNS MR1, MR2 CHANGED TO SUIT	ISSUE 5 22-5-62 (57336) TITLE AMENDED RELAY PC DELETED (G98C)	ISSUE 6 30-10-63	ORIGINATED BY AE1	DATE 29. 4. 59	SIGNED FOR COMMITTEE <i>[Signature]</i>
--	---	--	---	---	---------------------	----------------------	-------------------	--