

**V4 TELEPHONE REPEATER  
24V4D REPEATER MOUNTING SHELF  
DESCRIPTION**

**1. GENERAL**

**1.001** This addendum supplements Section 332-105-104, Issue 1.

**1.002** This addendum is issued to correct a numbering error on the P/0 TS1 terminal strip in Fig. 3.

**1.003** The following change applies to Fig. 3:

(a) On the P/0 TS1 located at the extreme left-hand side of Fig. 3, change the designation of the lead connected to terminal 44 from "S or D" to "B or D".