



305-Type Connectors Description, Use, Installation, and Repair Procedures

1. Overview

1.001 This addendum supplements AT&T 201-208-109, Issue 1. Place this pink sheet ahead of Page 1 of the practice.

1.002 This addendum is issued to show the discontinued availability of the 305-type connectors and show the recommended replacements, the 310- or 311-type connectors.

2. Changes

Issue 1 Changes

2.001 On Page 2, Part 1, replace paragraph 1.01 with the following.

2.002 This practice covers the description, use, installation, and repair procedures for 305-type connectors. The 305-type connectors are rated DA (Discontinued Availability) effective June 1, 1992. Recommended replacements are the 310- or 311-type connectors.