



309-Type Connectors Description, Use, Installation, and Repair Procedures

1. Overview

- 1.001 This addendum supplements AT&T 201-208-112, Issue 1. Place this pink sheet ahead of Page 1 of the practice.
- 1.002 This addendum is issued to correct and clarify the procedures for removing the terminals.

2. Changes

Issue 1 Changes

- 2.001 On Page 28, replace part 1 of paragraph 4.07 with the following:

To remove the 843826447 or 846587384 cross-connect tip or ring terminal (Figure 18), proceed as follows:
- 2.002 On Page 30, add the following Steps (3) and (4) to paragraph 4.11:
 - (3) Using the B long-nose pliers, close the tangs or barbs on the 842360976 or 846587293, or break the terminal flush with the back of the connector.
 - (4) Follow the procedure outlined in paragraph 4.09, Step (4).