## DROPS 19, 35 AND 56 TYPES REQUIREMENTS (CONDENSED SECTION FOR 032-340-701)

## 1. REQUIREMENTS (ALSO SEE SECTION 020-012-711)

- 1.01 Armature Movement:
  - (a) Move freely on its bearings.
  - (b) Side play measured in line with axis of pivots Max. .005".
- 1.02 Shutter Movement

  Move freely on its bearing pin.
- 1.03 Tripping Latch Position
  - (a) No obstruction interfering with free movement of tripping latch.
  - (b) Not touch sides of slot in shutter and mounting plate with armature and shutter side play taken up in opposite directions.
- 1.04 Night Bell Spring Clearance—Fig. 1(A)

  Clearance between night bell spring and contact wire with shutter held by tripping latch—.005".
  - 1.05 Shutter Clearance—Fig. 1(B)
    - (a) Clearance between closest point on top edge of shutter and shutter hinge plate with shutter held by tripping latch—.015". Use the No. 66D gauge.
    - (b) Drops Equipped With Protruding Night Bell Spring
      Mounting Screws Only—Clearance between closest
      point of top edge of shutter and shutter hinge plate with
      shutter held against night bell spring mounting screw—
      .005".




Fig. 1