209-TYPE RELAY

AND

ASSOCIATED 18-TYPE CONNECTING BLOCKS PIECE-PART DATA AND REPLACEMENT PROCEDURES

1. GENERAL

ν.

- 1.001 This addendum supplements Section 040-231-801, Issue 3.
- 1.002 This addendum is issued to change the piece-part number of a washer used on

the terminal block, Fig. 5. Present piece-part number of washer is P-213287.

The new piece-part number for this washer is P-284192.

Mmerican Telephone and Telegraph Company, 1972
Printed in U.S.A.

an Arak

Page 1 1 Page

a state while the state in