

**SERVICE**  
**513-, 514-, AND 515-TYPE KEY SERVICE UNITS**  
**IDENTIFICATION, CONNECTION, AND MAINTENANCE**  
**1A2 KEY TELEPHONE SYSTEM**

**1. GENERAL**

**1.001** This addendum supplements Section 518-215-405, Issue 7. Place this pink sheet ahead of Page 1 of the section.

**1.002** This addendum is issued to add information related to the Federal Communications Commission's (FCC) Registration Program.

**2. CHANGES TO SECTION**

**2.001** On Page 6, following paragraph 1.02, add the following:

**1.03** The 513-, 514-, and 515-type key service units (KSUs) have not been registered with

the FCC and new units will not be manufactured after January 1, 1980. Also after January 1, 1980, connection of customer-provided equipment (CPE) or telephone company-provided equipment requires the use of a 33B voice coupler when providing music-on-hold and a 401B, 415B, 471C, and 479C key telephone units (KTUs) when providing their related services. Previously connected or Class C units may be used for additions and maintenance at grandfathered installations for the life of the equipment, provided they are not modified. Class C stock may also be used in new installations after January 1, 1980.

**NOTICE**

Not for use or disclosure outside the  
Bell System except under written agreement