BELL SYSTEM PRACTICES
Station Operations Manual
General
Local Test Room Operation
General
Plant Assignment
Subscriber Plant Assignment
SUPPLY OPERATING PRACTICES
Plant Supplies

SECTION C16.902 SECTION F14.511.1 SECTION M25.05.1 SOP22.201.1 Issue A, 11-1-57-N TPT&TCo

TELEPHONE SET REQUIREMENTS (FORM P-2255)

1. GENERAL

- 1.01 This practice tells about Form P-2255, Telephone Set Requirements, and how to use it.
- 1.02 The PSC uses these forms to show the supplyman what equipment the installer needs to complete his work orders for simple service.

2. PREPARING FORM P-2255

- 2.01 The service order router in the PSC will make up Form P-2255 to show the installer's name, route or stall number and the PSC name. (See Fig. 1)
- 2.02 Check each service order for the transmission zone code and the type and color of equipment. Make a tally for each item of equipment in the proper space on the form.
- 2.03 For offices requiring station identification, tally equipment for tip stations, such as 2 party tip, in the "Tip" column. Tally all other equipment in the "Ring" column.
- 2.04 For offices not requiring station identification, tally all equipment in the "Ring" column.
- 2.05 List any telephone sets for simple service, not shown on Form P-2255, on a Form P-2170A. Staple it to the back of Form P-2255.

- 2.06 Where daily delivery of supplies is made from an SDC, send Form P-2255 to arrive at the supply center by 7:00 PM or a time mutually agreed on by the chief line assigner and supply foreman.
- 2.07 Where delivery of supplies is not made daily from an SDC, prepare Form P-2255 to show "Estimated Telephone Set Requirements" from one scheduled delivery to another, based on the number of sets used since the last delivery. Send this form to the supplies center in time for them to furnish your order on the next delivery date.
- 2.08 The supplyman will send the Form P-2255 along with the equipment ordered for each route.

3. ORDERING AND RETURNING SETS BY FIELD CRAFTSMEN

- 3.01 Field craftsmen shall:
 - (a) Make up Form P-2170A (Order for Material from Supplies Distribution Center) to order sets from the supply storeroom for maintenance replacements or truck stocks when not ordered on Form P-2255.
 - (b) Return all unused sets to the SDC so they will be available for reissue. Tag them unused.

Note: Leave unused sets in their original containers. Don't put these containers in tote boxes or canvas bags because these are used to send material back to San Leandro.

Fig. 1

Form P-2255

IN	ISTAI	LER,	ROL	JTE O	R ST/	LL #	<u> 5</u>	Wall	سه				P.S	s.c		Pa	10	ALT	9			D	ATE	9-1	0-3	57
	COMBINED SET HB				COMBINED SET HW				COIN COLLECTOR				GO	EXTE	NSION	ELL	HAND SET HU			HAND SET HC			SUBSCRIBER SET			
2	DIAL					DIAL				PREPAY		POST PAY					DIAL		T	DIAL						
	T	R	TUBE	MANUAL	т	R	TUBE	MANUAL	DIAL	MANUAL	DIAL	MANUAL	COND	TUBE	COND	TUBE	T	R	MANUAL	Ť	R	MANUAL		T	R	TUB
2		///											/													
5		/	//																							
•																										
Т	304	302	ST	ANDA	RD S	TATIC	ON E	QUIPN		IS L 91			ST -	SUE	STIT	UTIO	NS SI	ECON	1D -	SEE	NOTE	<u> </u>	2, & :	3		
2	5304 (a)	5302 (a)	02 306	ATUS	354		356	ATUS	197 (d)		193 (d)	182 (d)					212B	211	ATUS	203	202	ATUS	684BC	634CE	684A 684BA	634A
5	50	500		APPARA BLANK	5	554 556		APPARATUS BLANK	223 (b)		212 (b)		392L 592A	592C	531A 687A	531C 687B	212LR 4		APPARATU BLANK	NO SET		APPARA1 BLANK		685A		686A
-	30	7	309	АФР		357 (c)		ADD	1	91 97 (e)	193 (e)	182 (e)						11 LR	ADD	202 A		634 YD		634 YDT		
								50-IV	ory			N	OTE	5:					l							
							/	3 4	51-M	OSS GREE	EN		1. 5 2	5 Zone equipment can only be used in zone 2 when 2 zone equipment is not available.												
									53-C	herry Re	ed		2. But use 5 zone equipment only in zone 5.													
			/						54-M	lahogan)	Brown	n														
									55-R	ose Beig	je		For station identification, indicate Tip (T) or Ring (R). Otherwise order ring equipment. (C) 1770 to a section (Course Country and the indicate Tip (T) to a section (C) 1770 to a section (C)													
							-	\$11.00	56-P	astel Ye	llow															
									58-White			(a) 5	(a) 5300 type sets are for zone 2 customers authorized 500 type sets.													
		NC1/NL 512E 8-5/8"				10-7/8"			59-Rose Pin				(b) F	(b) Requires 685A sub. set.												
			16.	15 8-5 8")					60-Light Beige			(c) A	(c) Add 634AT sub. set to provide tube ringing.													
		- ACTUAL STE		· -					61-Light Gray 62-Aqua Blue			(c),														