





WIRING OF COMM. BATT. HOTEL SET IND. COIL SIDE TONE REDUCING

14478



ON DIVIDED RINGING PARTY LINES THE REC. TERM. MUST BE REVERSED AT THE BINDING POSTS AT STATIONS WHERE THE TIP SIDE OF THE LINE IS CONNECTED TO THE SLEEVE BINDING POST OF THE TEL.



9-20-25
7-12-25
8-5-21
3-22-21

W. J. R.
A. D.

14478