

5	24
5	14
5	4
HA1	35
HB	45
-1	21
+1 P	11
T1	1
TA1	3
TB1	25
ST1	31
HAZ	41
-2	22
+2	12
T2	2
TA2	6
TB2	26
ST2	32
HB2	42

NOTE 5

TO I D F LOCAL

TO DIAL TONE SUPPRESSION COT GBW 1551Q OR EQUIV (WHEN REQD)

P	4	4
-	4	14
-	4	24

NOTE 5


TO I D F MULT

COMMON SERVICES

MULT TO OTHER COTS ON RACK AS REQD

POS BATT	R-B
RING M/C START BATT	BK
O'FLOW BUSY TONE ETH	BK
SCA50	R-B
SCA39	BK
SCA10	BK

NOTE 2



NOTE 3


NOTE 4

NOTE

NOTES

1. ALL WIRING TO BE 22 SWG UNLESS OTHERWISE SPEC'D.
2. THESE LEADS ARE REQD ON 'SCA' ONLY
3. INSERT STRAP SHOWN ---3--- WHEN TRUNK OFFERING IS REQD.
4. INSERT STRAPS SHOWN ---1--- WHEN LINE POP CONTROL R 5 NO 1 IS FIRST CHOICE. INSERT STRAPS SHOWN ---2--- WHEN LINE FINDER CONTROL R 5 NO. 2 IS FIRST CHOICE.
5. WHEN GBW 1551Q IS PROVIDED USE CABLING SHOWN ---4--- AND DELETE CABLING SHOWN ---5---

LH (REAR) PLATE TERMINAL



FROM FUSE PANEL

U/A X. N° NZ 13. INCOMING JUNCTION FROM PARENT OR NON-DEPENDENT EXCH

AMENDMENT PARTICULARS

ISSUE DATE APPR

GBU 1398f

NEZ P.Q.

DRW

CHKD

ISSD

CHECK