

FIG. 1A. FUSE ALARM




FIG. 2A. PG. ALARM




FIG. 3A. BATT. JACKS





FIG. 4A. N.U. TONE DISTRIBUTION UNALLOTTED, CEASED OR T.O.S. LINES



NOTES:
 1. WHEN EXCHANGE COMPRISES MORE THAN ONE UNIT THE 2ND & 3RD UNITS ARE NOT EQUIPPED WITH RING TONE, PULSE DIST^N & CODE RINGING EQUIPMENT BUT DERIVE THE COMMON SERVICES FROM THE 1ST UNIT (R.1) THE 2ND & 3RD UNITS (R.2 & R.3) TO HAVE STRAP 78-98 REMOVED. THE ALARM LAMPS & PRESS BUTTON ON THE 1ST (R.1) UNIT ARE THEN EFFECTIVE FOR THE 2ND & 3RD (R.2 & R.3) UNITS.
 2. EXCEPT WHERE OTHERWISE STATED ALL WIRING BEARING A COLOUR CODE TO BE 20S.W.G. LOCAL PLATE STRAPPING TO BE 25S.W.G.

NZ. NOTES:
 A. TO N.Z.P.O. MISC. CIRCUITS WHEN REQD.

COMMON SERVICES RACK WIRING U.A.X. N.Z. 13R			
NZ. NOTE A WAS NOTE 1	(72552)	1B	2.4.64 Dgk
NZ. NOTE A ADDED	(48005)	1A	2.11.61 Dgk
	(34727)	1	17.12.54 Cud
AMENDMENT PARTICULARS	ISSUE DATE	APP	SIZE L 50V G
N.Z.P.O.	AM	13.1.64	GBW. 13700

FIG. 9A CONTINUOUS RINGING & LINE TESTER JACK




FIG. 9B 1-PER RACK

FIG. 10A TIME PULSE RELEASE




FIG. 10B 1-PER RACK

FIG. 11A MACHINE START




FIG. 11B 1-PER RACK

FIG. 12A OVERFLOW BUSY TONE - 900




FIG. 12B 1-PER RACK

COMMON SERVICES			
RACK WIRING			
U.A.X. N.Z. 13 R			
AMENDMENT PARTICULARS		ISSUE DATE	APP'D
NZ NOTE A REF WAS NZ NOTE 1 (72552)		18/22/64	DBH
NZ NOTE 1 REF ADDED (48005)		2/11/61	DBH
(34727)		17/12/56	DBH
SIZE		50%	
GBW 13700			
NZ POX	AM WS	SHEET 3 OF 5	

