


NOTES:-

1. FUSING NEGATIVE BATT. 1.5A.
POSITIVE BATT. 0.5A.
2. ALL WIRING TO BE 20 SWG UNLESS OTHERWISE SPECIFIED.



OBSOLETE

RESET (KR) $\frac{2}{2}$ + TEST (KT) $\frac{2}{2}$		<input type="checkbox"/> SLOW RELEASE <input checked="" type="checkbox"/> SLOW OPERATE	
POSITIVE BATTERY LOW VOLTAGE ALARM CIRCUIT ROTARY EXCHANGES			
OBSOLESCENCE NOTE ADDED (5065A) 2 14.12.62 OBH (68168) 1 13.11.56 KWT		SIZE F 5.0V W	
AMENDMENT PARTICULARS		ISSUE DATE APPD	
N7 P0		DRAWN CHECKED WIRING CIRCUIT	
GBW 14750		10 15 20	