

FIG. 1
FOR BATT & ETHS SEE INSET FIGURE




FIG. 2
FOR BATT & ETHS
SEE INSET
FIGURE

- NOTES:
1. FUSE - FIGS 1 & 2 1-5A.
 2. ALL WIRING TO BE 25 S.W.G. UNLESS OTHERWISE SPECIFIED.
 3. FOR WIRING SEE ASSOCIATED COMMON SERVICES DIAGRAM GBW15890 OR EQUIV.
 4. RELAY DR IS DIFFERENTIALLY CONNECTED.

BATT. FUSE - V. 22S.W.G. - UI2 [382]
 ETH BAR - R. 22S.W.G. - UI1 [342]
 BATT. V. - UI2-R15-R25-Ae-LAe-CFe-CFAe-VAe-Xe-Ze-F5b-P5e-We-C6e-CAe-L5e-S5e-D6e
 ETH. R. - UI1-A23-AZ-B21-B1-B3-CD2-LS1-S1-S58-DRI-DRA4