

RELAY CODES & COMPONENTS LIST, **GBW 13981**


SHEET
1 OF 1

UAX NZ13 INCOMING JUNCTION FROM PARENT OR
NON-DEPENDENT EXCHANGE

RELAY	3CC CODE	DIAG FIG.	NOTES	COMPT DESIGNATION	BPO CODE	NOTES
1BA 2BA	20541			RIA	Nº9	
1LA 2LA	1826			RIB	Nº9	
1HB 2HB	1630		B	R2	Nº12	
1HA 2HA	1630		B	(MRI)		HS1009 OR EQUIV.
1K 2K	1904					
1P 2P	15260					
1JA 2JA	1397					

NOTES: - A SPECIAL FACTORS OF SAFETY B SPECIAL ADJUSTMENTS C CIRCUIT POINTS OR MODIFICATIONS

LAYOUT



NZPO (4731) 7.8.6 A.6.

ISSUE 1
RELAYS 1P&2P
WHERE SHOWN
AS 15620

ISSUE 2 16.664
LAYOUT WAS
SHOWN AS 18
MOUNTING POSNS
(89.760)

ISSUE 3 28.764
R1/R2/R3 CHANGED
IN LAYOUT TO
RIA/IB/R2(58098)

ISSUE 4 26.766

ORIGINATED BY A.T.C.E. CLD

DATE 5-7-63

SIGNED FOR COMMITTEE HB