

RELAY CODES & COMPONENTS LIST, **GBW 16830**  
UAX NZ13 OUTGOING JUNCTION TO NON-DEPENDENT AUTO  
EXCHANGE WITH 1/2 JUNCTION BARRING FACILITY.

RELAY	BCC CODE	DIAG. FIG.	NOTES	COMP. DESIGNATION	BPO CODE	NOTES
A	HSD702			R1	Nº9	
D	70130			R7	Nº9	
BB	10163			(R6)	Nº6	
DD	4214			(R8)	Nº16GD.	
MH	15221			RBI	Nº1	BARRETT
CC	4016			MR1	2P/6AZ	
PR	6066			MR2	4/6AZ	
TM	1744			MR3	2P/6AZ	
B	21159			MR4		IN 4003 OR EQUIV. MOUNTED ON TM RELAY.
CD	11160			TI		ATE CODE L95927
HA	71552			C1	102C	
NU	74582			C2	102C	
CB	1731			C3+R6	101	
BA	2065					

NOTES:- A SPECIAL FACTORS OF SAFETY B SPECIAL ADJUSTMENTS C CIRCUIT POINTS OR MODIFICATIONS

LAYOUT

RBI + R1  
 A + R7  
 + C1 NU  
 B C2 TM  
 BA D PR  
 BB DD HA  
 + MR1/3 CB  
 C3 MH  
 CD TI  
 CC

F 1 STRIP CONNECTION  
 (Nº121A MOUNTED  
 AT THE REAR.)  
 MR2  
 T3

N.Z.P.O. 10-7-67 (83514) 26

ISSUE 1  
 NU RELAY ADDED TO LAYOUT.  
 ISSUE 2: 27-4-66.  
 MH RELAY WAS 5498, R7 WAS 112 (89049)  
 ISSUE 3:  
 20-6-68 RC  
 MR4 ADDED (68359)  
 ISS. 3A, 17.12.74 JHE

ORIGINATED BY A.T.&E.CO.  
 DATE 30.3.65  
 SIGNED FOR COMMITTEE AB

5 Centimetres

10

15

20

25

30