

NOTES:

- 1. LINE SWITCH REMOVED FROM 581A TELEPHONE SET BASE AND INSTALLED IN CUSTOMER-SUPPLIED DESK STAND.
- 2. LEADS FURNISHED WITH 840151054 PARTS GROUP, FIG. 1.
 3. WIRED FOR TIP PARTY SERVICE, WITH NO IDENT GRO.
 4. PIA RINGERS MANUFACTURED AFTER 10-1-72 ARE NOT PROVIDED WITH (BL) RINGER LEADS.
 5. NOT FURNISHED WITH TELEPHONE SET BASE, ORDERED SEPARATELY, SEE ORDERING GUIDE.

- INSULATED AND STORED 4010B NETWORK ONLY
- DP DIAL PULSE CONTACT
- ON DIAL OFF NORMAL CONTACT

Candlestick Type Telephone Set Connections (With D6AA Mounting Cord)